



Company: Den Caney Coaches Ltd - B32 3AH
 Location: All Vehicles
 Risk Assessment: Transport to / from destination
 Reference No. Vehicle Breakdown on Motorway
 Date of Assessment: 21/02/2012
 Completed By: James Clarke

Transport to / from destination

Identified hazard:

Embarking / Disembarking

No hazard icons entered

Who is at risk?

Members of the public / Driver

How is the risk controlled?

1. Vehicle to park at suitable point to enable safe disembarking / Embarking
2. Staff to disembark first to supervise Students (youth groups/schools)

No control icons entered

The calculated risk factor for this task/operation is **81** (Probability: 9 x Severity: 9)

This is classed as a **HIGH** risk

Additional Measures:

Further Measures	Person Responsible	Date For Completion
None Required		

Review Date 14/02/2013

Name..... Signature/s.....

Date.....