



Company: Den Caney Coaches Ltd
 Location: All Vehicles
 Risk Assessment: Transport to / from destination
 Reference No. Vehicle Breakdown on Motorway
 Date of Assessment: 14/02/2010
 Completed By: James Clarke

Transport to / from destination

Identified hazard:

Embarking / Disembarking

No hazard icons
entered

Who is at risk?

Members of the public / Driver

How is the risk controlled?

1. Vehicle to park at suitable point to enable safe disembarking / Embarking
2. Staff to disembark first to supervise Students (youth groups/schools)

No control icons
entered

The calculated risk factor for this task/operation is **81** (Probability: 9 x Severity: 9)

This is classed as a **HIGH** risk

Additional Measures:

Further Measure	Person Responsible	Date For Completion
None Required		

Review Date 14/02/2011

Name..... Signature/s.....

Date.....