



Company: Den Caney Coaches Ltd
 Location: All Vehicles
 Risk Assessment: Transport to / from destination
 Reference No. Vehicle Breakdown on Motorway
 Date of Assessment: 14/02/2010
 Completed By: James Clarke

Transport to / from destination

Identified hazard:

Vehicle breakdown on motorway

No hazard icons
entered

Who is at risk?

Members of the public / Driver

How is the risk controlled?

1. Nurse vehicle to safe place if possible
2. Evacuate the passengers to behind crash barriers.
3. Use Hazard Warning Lights
4. If immediate risk contact Highways Officers
5. Contact office for immediate assistance
6. Move passengers forward in coach if evacuation not suitable
7. Driver to wear Hi-Viz

No control icons
entered

The calculated risk factor for this task/operation is **16** (Probability: 2 x Severity: 8)

This is classed as a **MEDIUM** risk

Additional Measures:

Further Measure	Person Responsible	Date For Completion
None Required		

Review Date 14/02/2011

Name..... Signature/s.....

Date.....